

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 26,2016)**

Water Level of the accumulated water (at 12:00 on June 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,101 mm (185 mm decrease since 12:00 on June 25)	T.P.+ 1,384 mm (41 mm increase since 12:00 on June 25)	T.P.+ 1,322 mm (9 mm increase since 12:00 on June 25)	T.P.+ 1,433 mm (No change since 12:00 on June 25)
	Water level of Reactor Building	T.P.+ 1,452 mm (7 mm increase since 12:00 on June 25)	T.P.+ 1,492 mm (21 mm increase since 12:00 on June 25)	T.P.+ 1,340 mm (15 mm decrease since 12:00 on June 25)	T.P.+ 1,318 mm (1 mm increase since 12:00 on June 25)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 842 mm (141 mm decrease since 12:00 on June 25) T.P.+ 454 mm (220 mm decrease since 12:00 on June 25) T.P.+ 2,858 mm (15 mm increase since 12:00 on June 25)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.