

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on July 12,2016)**

Water Level of the accumulated water (at 12:00 on July 12)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,197 mm (25 mm increase since 12:00 on July 11)	T.P.+ 1,395 mm (2 mm increase since 12:00 on July 11)	T.P.+ 1,475 mm (22 mm increase since 12:00 on July 11)	T.P.+ 1,537 mm (9 mm increase since 12:00 on July 11)
	Water level of Reactor Building	T.P.+ 1,418 mm (1 mm increase since 12:00 on July 11)	T.P.+ 1,501 mm (14 mm decrease since 12:00 on July 11)	T.P.+ 1,446 mm (17 mm increase since 12:00 on July 11)	T.P.+ 1,343 mm (5 mm increase since 12:00 on July 11)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 714 mm (3 mm increase since 12:00 on July 11) T.P.+ 507 mm (158 mm decrease since 12:00 on July 11) T.P.+ 2,724 mm (7 mm increase since 12:00 on July 11)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.