

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on July 19,2016)**

Water Level of the accumulated water (at 12:00 on July 19)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,225 mm (22 mm increase since 12:00 on July 18)	T.P.+ 1,364 mm (26 mm decrease since 12:00 on July 18)	T.P.+ 1,474 mm (23 mm increase since 12:00 on July 18)	T.P.+ 1,559 mm (2 mm increase since 12:00 on July 18)
	Water level of Reactor Building	T.P.+ 1,414 mm (25 mm decrease since 12:00 on July 18)	T.P.+ 1,499 mm (20 mm decrease since 12:00 on July 18)	T.P.+ 1,441 mm (26 mm increase since 12:00 on July 18)	T.P.+ 1,366 mm (3 mm increase since 12:00 on July 18)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building  High Temperature Incinerator Building  On-site Bunker Building	T.P.+ 740 mm (1 mm decrease since 12:00 on July 18)  T.P.+ 457 mm ( 1 mm increase since 12:00 on July 18)  T.P.+ 2,768 mm (6 mm increase since 12:00 on July 18)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.