

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on July 25,2016)**

Water Level of the accumulated water (at 12:00 on July 25)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,221 mm (54 mm decrease since 12:00 on July 24)	T.P.+ 1,352 mm (32 mm decrease since 12:00 on July 24)	T.P.+ 1,434 mm (37 mm decrease since 12:00 on July 24)	T.P.+ 1,552 mm (3 mm decrease since 12:00 on July 24)
	Water level of Reactor Building	T.P.+ 1,413 mm (14 mm decrease since 12:00 on July 24)	T.P.+ 1,484 mm (4 mm increase since 12:00 on July 24)	T.P.+ 1,418 mm (14 mm decrease since 12:00 on July 24)	T.P.+ 1,379 mm (1 mm increase since 12:00 on July 24)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building  High Temperature Incinerator Building  On-site Bunker Building	T.P.+ -106 mm (138 mm decrease since 12:00 on July 24)  T.P.+ 389 mm ( 197 mm increase since 12:00 on July 24)  T.P.+ 2,809 mm (7 mm increase since 12:00 on July 24)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.