

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on August 13,2016)**

Water Level of the accumulated water (at 12:00 on August 13)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,306 mm (18 mm increase since 12:00 on August 12)	T.P.+ 1,381 mm (26 mm increase since 12:00 on August 12)	T.P.+ 1,348 mm (53 mm decrease since 12:00 on August 12)	T.P.+ 1,459 mm (6 mm decrease since 12:00 on August 12)
	Water level of Reactor Building	T.P.+ 1,453 mm (5 mm decrease since 12:00 on August 12)	T.P.+ 1,485 mm (5 mm increase since 12:00 on August 12)	T.P.+ 1,287 mm (40 mm decrease since 12:00 on August 12)	T.P.+ 1,352 mm (5 mm decrease since 12:00 on August 12)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -244 mm (49 mm increase since 12:00 on August 12) T.P.+ -180 mm ( 16 mm increase since 12:00 on August 12) T.P.+ 2,796 mm (217 mm decrease since 12:00 on August 12)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.