

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on August 24,2016)**

Water Level of the accumulated water (at 12:00 on August 24)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,469 mm (107 mm increase since 12:00 on August 23)	T.P.+ 1,479 mm (84 mm increase since 12:00 on August 23)	T.P.+ 1,518 mm (30 mm increase since 12:00 on August 23)	T.P.+ 1,438 mm (15 mm increase since 12:00 on August 23)
	Water level of Reactor Building	T.P.+ 1,478 mm (35 mm increase since 12:00 on August 23)	T.P.+ 1,580 mm (58 mm increase since 12:00 on August 23)	T.P.+ 1,364 mm (10 mm increase since 12:00 on August 23)	T.P.+ 1,318 mm (3 mm increase since 12:00 on August 23)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -196 mm (1 mm increase since 12:00 on August 23) T.P.+ 527 mm (204 mm decrease since 12:00 on August 23) T.P.+ 2,883 mm (14 mm increase since 12:00 on August 23)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.