

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on August 26,2016)**

Water Level of the accumulated water (at 12:00 on August 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,537 mm (34 mm increase since 12:00 on August 25)	T.P.+ 1,440 mm (42 mm decrease since 12:00 on August 25)	T.P.+ 1,493 mm (3 mm decrease since 12:00 on August 25)	T.P.+ 1,448 mm (4 mm increase since 12:00 on August 25)
	Water level of Reactor Building	T.P.+ 1,478 mm (27 mm decrease since 12:00 on August 25)	T.P.+ 1,587 mm (5 mm decrease since 12:00 on August 25)	T.P.+ 1,312 mm (17 mm decrease since 12:00 on August 25)	T.P.+ 1,329 mm (5 mm increase since 12:00 on August 25)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 167 mm (358 mm increase since 12:00 on August 25) T.P.+ 291 mm ( 553 mm decrease since 12:00 on August 25) T.P.+ 2,907 mm (12 mm increase since 12:00 on August 25)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.