

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on August 27,2016)**

Water Level of the accumulated water (at 12:00 on August 27)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,589 mm (52 mm increase since 12:00 on August 26)	T.P.+ 1,417 mm (23 mm decrease since 12:00 on August 26)	T.P.+ 1,503 mm (10 mm increase since 12:00 on August 26)	T.P.+ 1,448 mm (No change since 12:00 on August 26)
	Water level of Reactor Building	T.P.+ 1,453 mm (25 mm decrease since 12:00 on August 26)	T.P.+ 1,564 mm (23 mm decrease since 12:00 on August 26)	T.P.+ 1,327 mm (15 mm increase since 12:00 on August 26)	T.P.+ 1,333 mm (4 mm increase since 12:00 on August 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 179 mm (12 mm increase since 12:00 on August 26) T.P.+ 695 mm ( 404 mm increase since 12:00 on August 26) T.P.+ 2,920 mm (13 mm increase since 12:00 on August 26)		
Notes					

For quick publication of the data of water level, values are provided as reference values.