

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on September 23,2016)**

Water Level of the accumulated water (at 12:00 on September 23)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,481 mm (37 mm increase since 12:00 on September 22)	T.P.+ 1,745 mm (17 mm decrease since 12:00 on September 22)	T.P.+ 1,674 mm (42 mm increase since 12:00 on September 22)	T.P.+ 1,610 mm (33 mm increase since 12:00 on September 22)
	Water level of Reactor Building	T.P.+ 1,444 mm (22 mm increase since 12:00 on September 22)	T.P.+ 1,874 mm (5 mm increase since 12:00 on September 22)	T.P.+ 1,485 mm (49 mm increase since 12:00 on September 22)	T.P.+ 1,414 mm (8 mm increase since 12:00 on September 22)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building  High Temperature Incinerator Building  On-site Bunker Building	T.P.+ 2,673 mm (12 mm increase since 12:00 on September 22)  T.P.+ 793 mm ( 308 mm increase since 12:00 on September 22)  T.P.+ 2,857 mm (8 mm increase since 12:00 on September 22)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.