

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 26,2016)**

Water Level of the accumulated water (at 12:00 on October 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,357 mm (28 mm increase since 12:00 on October 25)	T.P.+ 1,474 mm (39 mm increase since 12:00 on October 25)	T.P.+ 1,436 mm (7 mm decrease since 12:00 on October 25)	T.P.+ 1,675 mm (17 mm decrease since 12:00 on October 25)
	Water level of Reactor Building	T.P.+ 1,462 mm (6 mm decrease since 12:00 on October 25)	T.P.+ 1,564 mm (40 mm increase since 12:00 on October 25)	T.P.+ 1,448 mm (35 mm decrease since 12:00 on October 25)	T.P.+ 1,567 mm (13 mm decrease since 12:00 on October 25)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 3,454 mm (96 mm decrease since 12:00 on October 25) T.P.+ 51 mm (147 mm decrease since 12:00 on October 25) T.P.+ 2,790 mm (6 mm increase since 12:00 on October 25)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.