

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on March 16,)**

Water Level of the accumulated water (at 0:00 on March 16)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,030 mm (No change since 0:00 on March 15)	T.P.+ 1,152 mm (15 mm increase since 0:00 on March 15)	T.P.+ 974 mm (24 mm increase since 0:00 on March 15)	T.P.+ 1,089 mm (2 mm decrease since 0:00 on March 15)
	Water level of Reactor Building	T.P.+ 1,148 mm (4 mm decrease since 0:00 on March 15)	T.P.+ 1,126 mm (29 mm decrease since 0:00 on March 15)	T.P.+ 967 mm (23 mm increase since 0:00 on March 15)	T.P.+ 961 mm (1 mm decrease since 0:00 on March 15)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 2,541 mm (50 mm increase since 0:00 on March 15) #VALUE! #VALUE!		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.