

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on March 18,)**

Water Level of the accumulated water (at 0:00 on March 18)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,045 mm (9 mm increase since 0:00 on March 17)	T.P.+ 1,126 mm (9 mm decrease since 0:00 on March 17)	T.P.+ 970 mm (1 mm increase since 0:00 on March 17)	T.P.+ 1,092 mm (No change since 0:00 on March 17)
	Water level of Reactor Building	T.P.+ 1,110 mm (13 mm decrease since 0:00 on March 17)	T.P.+ 1,162 mm (19 mm increase since 0:00 on March 17)	T.P.+ 962 mm (8 mm decrease since 0:00 on March 17)	T.P.+ 961 mm (No change since 0:00 on March 17)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 2,613 mm (No change since 0:00 on March 17) T.P.+ 341 mm (124 mm increase since 0:00 on March 17) T.P.+ 2,870 mm (7 mm increase since 0:00 on March 17)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.