

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on May 17,)**

Water Level of the accumulated water (at 0:00 on May 17)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,149 mm (No change since 0:00 on May 16)	T.P.+ 1,017 mm (15 mm increase since 0:00 on May 16)	T.P.+ 1,090 mm (3 mm increase since 0:00 on May 16)
	Water level of Reactor Building	T.P.+ 1,143 mm (3 mm increase since 0:00 on May 16)	T.P.+ 1,155 mm (67 mm decrease since 0:00 on May 16)	T.P.+ 1,003 mm (14 mm increase since 0:00 on May 16)	T.P.+ 970 mm (No change since 0:00 on May 16)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 997 mm (33 mm decrease since 0:00 on May 16) T.P.+ 18 mm (74 mm increase since 0:00 on May 16) T.P.+ 2,995 mm (8 mm increase since 0:00 on May 16)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.