

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on May 20,)**

Water Level of the accumulated water (at 0:00 on May 20)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,126 mm (3 mm decrease since 0:00 on May 19)	T.P.+ 1,021 mm (14 mm increase since 0:00 on May 19)	T.P.+ 1,093 mm (4 mm increase since 0:00 on May 19)
	Water level of Reactor Building	T.P.+ 1,127 mm (No change since 0:00 on May 19)	T.P.+ 1,148 mm (20 mm decrease since 0:00 on May 19)	T.P.+ 1,008 mm (12 mm increase since 0:00 on May 19)	T.P.+ 970 mm (No change since 0:00 on May 19)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 863 mm (78 mm decrease since 0:00 on May 19) T.P.+ 23 mm (1 mm increase since 0:00 on May 19) T.P.+ 3,011 mm (5 mm increase since 0:00 on May 19)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.