

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on May 21,)**

Water Level of the accumulated water (at 0:00 on May 21)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,124 mm (2 mm decrease since 0:00 on May 20)	T.P.+ 1,034 mm (13 mm increase since 0:00 on May 20)	T.P.+ 1,096 mm (3 mm increase since 0:00 on May 20)
	Water level of Reactor Building	T.P.+ 1,131 mm (4 mm increase since 0:00 on May 20)	T.P.+ 1,171 mm (23 mm increase since 0:00 on May 20)	T.P.+ 1,024 mm (16 mm increase since 0:00 on May 20)	T.P.+ 972 mm (2 mm increase since 0:00 on May 20)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 838 mm (25 mm decrease since 0:00 on May 20) T.P.+ 25 mm (2 mm increase since 0:00 on May 20) T.P.+ 2,739 mm (272 mm decrease since 0:00 on May 20)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.