

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on May 22,)**

Water Level of the accumulated water (at 0:00 on May 22)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,120 mm (4 mm decrease since 0:00 on May 21)	T.P.+ 1,047 mm (13 mm increase since 0:00 on May 21)	T.P.+ 1,099 mm (3 mm increase since 0:00 on May 21)
	Water level of Reactor Building	T.P.+ 1,135 mm (4 mm increase since 0:00 on May 21)	T.P.+ 1,171 mm (No change since 0:00 on May 21)	T.P.+ 1,034 mm (10 mm increase since 0:00 on May 21)	T.P.+ 973 mm (1 mm increase since 0:00 on May 21)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 807 mm (31 mm decrease since 0:00 on May 21) T.P.+ 27 mm (2 mm increase since 0:00 on May 21) T.P.+ 2,743 mm (4 mm increase since 0:00 on May 21)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.