

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on May 24,)**

Water Level of the accumulated water (at 0:00 on May 24)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,117 mm (2 mm decrease since 0:00 on May 23)	T.P.+ 1,014 mm (13 mm decrease since 0:00 on May 23)	T.P.+ 1,075 mm (15 mm decrease since 0:00 on May 23)
	Water level of Reactor Building	T.P.+ 1,138 mm (No change since 0:00 on May 23)	T.P.+ 1,168 mm (9 mm increase since 0:00 on May 23)	T.P.+ 999 mm (25 mm decrease since 0:00 on May 23)	T.P.+ 960 mm (12 mm decrease since 0:00 on May 23)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 859 mm (29 mm increase since 0:00 on May 23) T.P.+ 40 mm ( 12 mm increase since 0:00 on May 23) T.P.+ 2,751 mm (4 mm increase since 0:00 on May 23)		
Notes					

For quick publication of the data of water level, values are provided as reference values.