

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 12,)**

Water Level of the accumulated water (at 0:00 on June 12)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (1 mm decrease since 0:00 on June 11)	T.P.+ 979 mm (23 mm decrease since 0:00 on June 11)	T.P.+ 1,069 mm (11 mm decrease since 0:00 on June 11)
	Water level of Reactor Building	T.P.+ 1,117 mm (2 mm decrease since 0:00 on June 11)	T.P.+ 1,155 mm (7 mm decrease since 0:00 on June 11)	T.P.+ 966 mm (24 mm decrease since 0:00 on June 11)	T.P.+ 954 mm (4 mm decrease since 0:00 on June 11)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 758 mm (16 mm increase since 0:00 on June 11) T.P.+ 158 mm (4 mm increase since 0:00 on June 11) T.P.+ 2,742 mm (11 mm increase since 0:00 on June 11)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.