

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 13,)**

Water Level of the accumulated water (at 0:00 on June 13)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (No change since 0:00 on June 12)	T.P.+ 991 mm (12 mm increase since 0:00 on June 12)	T.P.+ 1,073 mm (4 mm increase since 0:00 on June 12)
	Water level of Reactor Building	T.P.+ 1,142 mm (25 mm increase since 0:00 on June 12)	T.P.+ 1,147 mm (8 mm decrease since 0:00 on June 12)	T.P.+ 978 mm (12 mm increase since 0:00 on June 12)	T.P.+ 954 mm (No change since 0:00 on June 12)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 669 mm (89 mm decrease since 0:00 on June 12) T.P.+ 164 mm ( 6 mm increase since 0:00 on June 12) T.P.+ 2,753 mm (11 mm increase since 0:00 on June 12)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.