

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 16,)**

Water Level of the accumulated water (at 0:00 on June 16)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (2 mm decrease since 0:00 on June 15)	T.P.+ 1,003 mm (11 mm decrease since 0:00 on June 15)	T.P.+ 1,074 mm (6 mm decrease since 0:00 on June 15)
	Water level of Reactor Building	T.P.+ 1,122 mm (1 mm increase since 0:00 on June 15)	T.P.+ 1,159 mm (5 mm decrease since 0:00 on June 15)	T.P.+ 990 mm (14 mm decrease since 0:00 on June 15)	T.P.+ 955 mm (1 mm increase since 0:00 on June 15)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 513 mm (3 mm decrease since 0:00 on June 15) T.P.+ 206 mm ( 32 mm increase since 0:00 on June 15) T.P.+ 2,783 mm (12 mm increase since 0:00 on June 15)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.