

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 17,)**

	Unit 1	Unit 2	Unit 3	Unit 4	
Water Level of the accumulated water (at 0:00 on June 17)	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (No change since 0:00 on June 16)	T.P.+ 1,018 mm (15 mm increase since 0:00 on June 16)	T.P.+ 1,077 mm (3 mm increase since 0:00 on June 16)
	Water level of Reactor Building	T.P.+ 1,126 mm (4 mm increase since 0:00 on June 16)	T.P.+ 1,152 mm (7 mm decrease since 0:00 on June 16)	T.P.+ 1,008 mm (18 mm increase since 0:00 on June 16)	T.P.+ 954 mm (1 mm decrease since 0:00 on June 16)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 425 mm (88 mm decrease since 0:00 on June 16) T.P.+ 210 mm (4 mm increase since 0:00 on June 16) T.P.+ 2,794 mm (11 mm increase since 0:00 on June 16)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.