

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 18,)**

Water Level of the accumulated water (at 0:00 on June 18)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,111 mm (1 mm increase since 0:00 on June 17)	T.P.+ 1,010 mm (8 mm decrease since 0:00 on June 17)	T.P.+ 1,080 mm (3 mm increase since 0:00 on June 17)
	Water level of Reactor Building	T.P.+ 1,126 mm (No change since 0:00 on June 17)	T.P.+ 1,131 mm (21 mm decrease since 0:00 on June 17)	T.P.+ 1,008 mm (No change since 0:00 on June 17)	T.P.+ 954 mm (No change since 0:00 on June 17)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 387 mm (38 mm decrease since 0:00 on June 17) T.P.+ 214 mm (4 mm increase since 0:00 on June 17) T.P.+ 2,805 mm (11 mm increase since 0:00 on June 17)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.