

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 19,)**

		Unit 1	Unit 2	Unit 3	Unit 4
Water Level of the accumulated water (at 0:00 on June 19)	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (1 mm decrease since 0:00 on June 18)	T.P.+ 971 mm (39 mm decrease since 0:00 on June 18)	T.P.+ 1,069 mm (11 mm decrease since 0:00 on June 18)
	Water level of Reactor Building	T.P.+ 1,131 mm (5 mm increase since 0:00 on June 18)	T.P.+ 1,147 mm (16 mm increase since 0:00 on June 18)	T.P.+ 959 mm (49 mm decrease since 0:00 on June 18)	T.P.+ 951 mm (3 mm decrease since 0:00 on June 18)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 431 mm (44 mm increase since 0:00 on June 18) T.P.+ 218 mm (4 mm increase since 0:00 on June 18) T.P.+ 2,815 mm (10 mm increase since 0:00 on June 18)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.