

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 23,)**

Water Level of the accumulated water (at 0:00 on June 23)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,113 mm (No change since 0:00 on June 22)	T.P.+ 991 mm (36 mm decrease since 0:00 on June 22)	T.P.+ 1,080 mm (5 mm decrease since 0:00 on June 22)
	Water level of Reactor Building	T.P.+ 1,120 mm (3 mm increase since 0:00 on June 22)	T.P.+ 1,136 mm (2 mm increase since 0:00 on June 22)	T.P.+ 961 mm (52 mm decrease since 0:00 on June 22)	T.P.+ 954 mm (No change since 0:00 on June 22)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 281 mm (42 mm increase since 0:00 on June 22) T.P.+ 235 mm ( 3 mm increase since 0:00 on June 22) T.P.+ 2,867 mm (15 mm increase since 0:00 on June 22)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.