

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 24,)**

Water Level of the accumulated water (at 0:00 on June 24)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,112 mm (1 mm decrease since 0:00 on June 23)	T.P.+ 1,006 mm (15 mm increase since 0:00 on June 23)	T.P.+ 1,081 mm (1 mm increase since 0:00 on June 23)
	Water level of Reactor Building	T.P.+ 1,111 mm (9 mm decrease since 0:00 on June 23)	T.P.+ 1,148 mm (12 mm increase since 0:00 on June 23)	T.P.+ 978 mm (17 mm increase since 0:00 on June 23)	T.P.+ 954 mm (No change since 0:00 on June 23)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 199 mm (82 mm decrease since 0:00 on June 23) T.P.+ 240 mm (5 mm increase since 0:00 on June 23) T.P.+ 2,887 mm (20 mm increase since 0:00 on June 23)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.