

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 25,)**

Water Level of the accumulated water (at 0:00 on June 25)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (2 mm decrease since 0:00 on June 24)	T.P.+ 1,020 mm (14 mm increase since 0:00 on June 24)	T.P.+ 1,085 mm (4 mm increase since 0:00 on June 24)
	Water level of Reactor Building	T.P.+ 1,116 mm (5 mm increase since 0:00 on June 24)	T.P.+ 1,148 mm (No change since 0:00 on June 24)	T.P.+ 992 mm (14 mm increase since 0:00 on June 24)	T.P.+ 953 mm (1 mm decrease since 0:00 on June 24)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 132 mm (67 mm decrease since 0:00 on June 24) T.P.+ 244 mm (4 mm increase since 0:00 on June 24) T.P.+ 2,900 mm (13 mm increase since 0:00 on June 24)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.