

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 26,)**

Water Level of the accumulated water (at 0:00 on June 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (No change since 0:00 on June 25)	T.P.+ 1,000 mm (20 mm decrease since 0:00 on June 25)	T.P.+ 1,069 mm (16 mm decrease since 0:00 on June 25)
	Water level of Reactor Building	T.P.+ 1,123 mm (7 mm increase since 0:00 on June 25)	T.P.+ 1,136 mm (12 mm decrease since 0:00 on June 25)	T.P.+ 971 mm (21 mm decrease since 0:00 on June 25)	T.P.+ 950 mm (3 mm decrease since 0:00 on June 25)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 140 mm (8 mm increase since 0:00 on June 25) T.P.+ 249 mm (5 mm increase since 0:00 on June 25) T.P.+ 2,913 mm (13 mm increase since 0:00 on June 25)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.