

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 27,)**

Water Level of the accumulated water (at 0:00 on June 27)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,109 mm (1 mm decrease since 0:00 on June 26)	T.P.+ 1,014 mm (14 mm increase since 0:00 on June 26)	T.P.+ 1,072 mm (3 mm increase since 0:00 on June 26)
	Water level of Reactor Building	T.P.+ 1,126 mm (3 mm increase since 0:00 on June 26)	T.P.+ 1,164 mm (28 mm increase since 0:00 on June 26)	T.P.+ 985 mm (14 mm increase since 0:00 on June 26)	T.P.+ 948 mm (2 mm decrease since 0:00 on June 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building  High Temperature Incinerator Building  On-site Bunker Building	T.P.+ 49 mm (91 mm decrease since 0:00 on June 26)  T.P.+ 252 mm ( 3 mm increase since 0:00 on June 26)  T.P.+ 2,925 mm (12 mm increase since 0:00 on June 26)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.