

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 28,)**

Water Level of the accumulated water (at 0:00 on June 28)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (1 mm increase since 0:00 on June 27)	T.P.+ 953 mm (82 mm decrease since 0:00 on June 27)	T.P.+ 1,075 mm (3 mm increase since 0:00 on June 27)
	Water level of Reactor Building	T.P.+ 1,125 mm (1 mm decrease since 0:00 on June 27)	T.P.+ 1,145 mm (19 mm decrease since 0:00 on June 27)	T.P.+ 989 mm (4 mm increase since 0:00 on June 27)	T.P.+ 948 mm (No change since 0:00 on June 27)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 13 mm (36 mm decrease since 0:00 on June 27) T.P.+ 255 mm (3 mm increase since 0:00 on June 27) T.P.+ 2,938 mm (13 mm increase since 0:00 on June 27)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.