

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on June 29,)**

Water Level of the accumulated water (at 0:00 on June 29)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,110 mm (No change since 0:00 on June 28)	T.P.+ 914 mm (39 mm decrease since 0:00 on June 28)	T.P.+ 1,063 mm (12 mm decrease since 0:00 on June 28)
	Water level of Reactor Building	T.P.+ 1,126 mm (1 mm increase since 0:00 on June 28)	T.P.+ 1,155 mm (10 mm increase since 0:00 on June 28)	T.P.+ 941 mm (48 mm decrease since 0:00 on June 28)	T.P.+ 945 mm (3 mm decrease since 0:00 on June 28)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 55 mm (42 mm increase since 0:00 on June 28) T.P.+ 259 mm (4 mm increase since 0:00 on June 28) T.P.+ 2,950 mm (12 mm increase since 0:00 on June 28)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.