

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on July 6,)**

Water Level of the accumulated water (at 0:00 on July 6)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 1,118 mm (No change since 0:00 on July 5)	T.P.+ 951 mm (15 mm increase since 0:00 on July 5)	T.P.+ 1,065 mm (5 mm increase since 0:00 on July 5)
	Water level of Reactor Building	T.P.+ 1,127 mm (11 mm increase since 0:00 on July 5)	T.P.+ 1,129 mm (9 mm decrease since 0:00 on July 5)	T.P.+ 978 mm (16 mm increase since 0:00 on July 5)	T.P.+ 940 mm (2 mm increase since 0:00 on July 5)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 80 mm (21 mm increase since 0:00 on July 5) T.P.+ 326 mm (1 mm increase since 0:00 on July 5) T.P.+ 2,758 mm (10 mm increase since 0:00 on July 5)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.