

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on July 27,)**

Water Level of the accumulated water (at 0:00 on July 27)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 945 mm (28 mm increase since 0:00 on July 26)	T.P.+ 849 mm (18 mm increase since 0:00 on July 26)	T.P.+ 970 mm (4 mm increase since 0:00 on July 26)
	Water level of Reactor Building	T.P.+ 1,026 mm (16 mm increase since 0:00 on July 26)	T.P.+ 1,019 mm (18 mm increase since 0:00 on July 26)	T.P.+ 877 mm (18 mm increase since 0:00 on July 26)	T.P.+ 855 mm (No change since 0:00 on July 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 274 mm (133 mm decrease since 0:00 on July 26) T.P.+ 472 mm (No change since 0:00 on July 26) T.P.+ 2,942 mm (8 mm increase since 0:00 on July 26)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.