

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 12,)**

Water Level of the accumulated water (at 0:00 on August 12)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 911 mm (No change since 0:00 on August 11)	T.P.+ 804 mm (14 mm increase since 0:00 on August 11)	T.P.+ 912 mm (3 mm increase since 0:00 on August 11)
	Water level of Reactor Building	T.P.+ 948 mm (5 mm decrease since 0:00 on August 11)	T.P.+ 944 mm (22 mm decrease since 0:00 on August 11)	T.P.+ 833 mm (16 mm increase since 0:00 on August 11)	T.P.+ 801 mm (2 mm decrease since 0:00 on August 11)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -33 mm (116 mm decrease since 0:00 on August 11) T.P.+ 610 mm (No change since 0:00 on August 11) T.P.+ 2,807 mm (6 mm increase since 0:00 on August 11)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.