

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 13,)**

Water Level of the accumulated water (at 0:00 on August 13)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 908 mm (3 mm decrease since 0:00 on August 12)	T.P.+ 796 mm (8 mm decrease since 0:00 on August 12)	T.P.+ 915 mm (3 mm increase since 0:00 on August 12)
	Water level of Reactor Building	T.P.+ 938 mm (10 mm decrease since 0:00 on August 12)	T.P.+ 956 mm (12 mm increase since 0:00 on August 12)	T.P.+ 836 mm (3 mm increase since 0:00 on August 12)	T.P.+ 801 mm (No change since 0:00 on August 12)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -130 mm (97 mm decrease since 0:00 on August 12) T.P.+ 610 mm ( No change since 0:00 on August 12) T.P.+ 2,813 mm (6 mm increase since 0:00 on August 12)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.