

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 16,)**

Water Level of the accumulated water (at 0:00 on August 16)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 907 mm (No change since 0:00 on August 15)	T.P.+ 811 mm (21 mm increase since 0:00 on August 15)	T.P.+ 912 mm (3 mm increase since 0:00 on August 15)
	Water level of Reactor Building	T.P.+ 945 mm (9 mm increase since 0:00 on August 15)	T.P.+ 972 mm (9 mm increase since 0:00 on August 15)	T.P.+ 838 mm (19 mm increase since 0:00 on August 15)	T.P.+ 800 mm (No change since 0:00 on August 15)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -436 mm (126 mm decrease since 0:00 on August 15) T.P.+ 611 mm ( No change since 0:00 on August 15) T.P.+ 2,836 mm (8 mm increase since 0:00 on August 15)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.