

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 17,)**

Water Level of the accumulated water (at 0:00 on August 17)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 910 mm (3 mm increase since 0:00 on August 16)	T.P.+ 801 mm (10 mm decrease since 0:00 on August 16)	T.P.+ 916 mm (4 mm increase since 0:00 on August 16)
	Water level of Reactor Building	T.P.+ 957 mm (12 mm increase since 0:00 on August 16)	T.P.+ 951 mm (21 mm decrease since 0:00 on August 16)	T.P.+ 843 mm (5 mm increase since 0:00 on August 16)	T.P.+ 798 mm (2 mm decrease since 0:00 on August 16)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -532 mm (96 mm decrease since 0:00 on August 16) T.P.+ 611 mm (No change since 0:00 on August 16) T.P.+ 2,845 mm (9 mm increase since 0:00 on August 16)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.