

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 18,)**

Water Level of the accumulated water (at 0:00 on August 18)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 910 mm (No change since 0:00 on August 17)	T.P.+ 795 mm (6 mm decrease since 0:00 on August 17)	T.P.+ 912 mm (4 mm decrease since 0:00 on August 17)
	Water level of Reactor Building	T.P.+ 936 mm (21 mm decrease since 0:00 on August 17)	T.P.+ 961 mm (10 mm increase since 0:00 on August 17)	T.P.+ 821 mm (22 mm decrease since 0:00 on August 17)	T.P.+ 798 mm (No change since 0:00 on August 17)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -575 mm (43 mm decrease since 0:00 on August 17) T.P.+ 612 mm ( 1 mm increase since 0:00 on August 17) T.P.+ 2,857 mm (12 mm increase since 0:00 on August 17)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.