

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 19,)**

Water Level of the accumulated water (at 0:00 on August 19)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 910 mm (No change since 0:00 on August 18)	T.P.+ 809 mm (14 mm increase since 0:00 on August 18)	T.P.+ 915 mm (3 mm increase since 0:00 on August 18)
	Water level of Reactor Building	T.P.+ 947 mm (11 mm increase since 0:00 on August 18)	T.P.+ 935 mm (26 mm decrease since 0:00 on August 18)	T.P.+ 840 mm (19 mm increase since 0:00 on August 18)	T.P.+ 797 mm (1 mm decrease since 0:00 on August 18)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -572 mm (3 mm increase since 0:00 on August 18) T.P.+ 618 mm (6 mm increase since 0:00 on August 18) T.P.+ 2,870 mm (13 mm increase since 0:00 on August 18)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.