

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 24,)**

Water Level of the accumulated water (at 0:00 on August 24)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 885 mm (20 mm increase since 0:00 on August 23)	T.P.+ 792 mm (25 mm increase since 0:00 on August 23)	T.P.+ 902 mm (4 mm increase since 0:00 on August 23)
	Water level of Reactor Building	T.P.+ 938 mm (9 mm increase since 0:00 on August 23)	T.P.+ 968 mm (23 mm increase since 0:00 on August 23)	T.P.+ 821 mm (26 mm increase since 0:00 on August 23)	T.P.+ 787 mm (No change since 0:00 on August 23)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 41 mm (2 mm increase since 0:00 on August 23) T.P.+ 631 mm (1 mm increase since 0:00 on August 23) T.P.+ 2,937 mm (13 mm increase since 0:00 on August 23)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.