

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 25,)**

Water Level of the accumulated water (at 0:00 on August 25)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 900 mm (15 mm increase since 0:00 on August 24)	T.P.+ 823 mm (31 mm increase since 0:00 on August 24)	T.P.+ 908 mm (6 mm increase since 0:00 on August 24)
	Water level of Reactor Building	T.P.+ 949 mm (11 mm increase since 0:00 on August 24)	T.P.+ 935 mm (33 mm decrease since 0:00 on August 24)	T.P.+ 851 mm (30 mm increase since 0:00 on August 24)	T.P.+ 788 mm (1 mm increase since 0:00 on August 24)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 44 mm (3 mm increase since 0:00 on August 24) T.P.+ 630 mm (1 mm decrease since 0:00 on August 24) T.P.+ 2,951 mm (14 mm increase since 0:00 on August 24)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.