

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 27,)**

Water Level of the accumulated water (at 0:00 on August 27)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 903 mm (1 mm increase since 0:00 on August 26)	T.P.+ 776 mm (26 mm decrease since 0:00 on August 26)	T.P.+ 902 mm (2 mm increase since 0:00 on August 26)
	Water level of Reactor Building	T.P.+ 945 mm (7 mm decrease since 0:00 on August 26)	T.P.+ 959 mm (14 mm decrease since 0:00 on August 26)	T.P.+ 819 mm (30 mm decrease since 0:00 on August 26)	T.P.+ 784 mm (1 mm decrease since 0:00 on August 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 351 mm (185 mm increase since 0:00 on August 26) T.P.+ 632 mm (No change since 0:00 on August 26) T.P.+ 2,721 mm (244 mm decrease since 0:00 on August 26)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.