

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on August 30,)**

Water Level of the accumulated water (at 0:00 on August 30)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 908 mm (No change since 0:00 on August 29)	T.P.+ 790 mm (15 mm increase since 0:00 on August 29)	T.P.+ 910 mm (2 mm increase since 0:00 on August 29)
	Water level of Reactor Building	T.P.+ 931 mm (15 mm decrease since 0:00 on August 29)	T.P.+ 940 mm (3 mm increase since 0:00 on August 29)	T.P.+ 819 mm (14 mm increase since 0:00 on August 29)	T.P.+ 784 mm (No change since 0:00 on August 29)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 587 mm (67 mm increase since 0:00 on August 29) T.P.+ 649 mm (No change since 0:00 on August 29) T.P.+ 2,752 mm (11 mm increase since 0:00 on August 29)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.