

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 16,)**

Water Level of the accumulated water (at 0:00 on September 16)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 905 mm (No change since 0:00 on September 15)	T.P.+ 717 mm (3 mm decrease since 0:00 on September 15)	T.P.+ 892 mm (2 mm increase since 0:00 on September 15)
	Water level of Reactor Building	T.P.+ 947 mm (2 mm decrease since 0:00 on September 15)	T.P.+ 965 mm (5 mm decrease since 0:00 on September 15)	T.P.+ 746 mm (19 mm decrease since 0:00 on September 15)	T.P.+ 773 mm (1 mm decrease since 0:00 on September 15)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 467 mm (134 mm decrease since 0:00 on September 15) T.P.+ 748 mm (56 mm increase since 0:00 on September 15) T.P.+ 3,077 mm (46 mm increase since 0:00 on September 15)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.