

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 21,)**

Water Level of the accumulated water (at 0:00 on September 21)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 920 mm (4 mm increase since 0:00 on September 20)	T.P.+ 753 mm (3 mm decrease since 0:00 on September 20)	T.P.+ 892 mm (3 mm increase since 0:00 on September 20)
	Water level of Reactor Building	T.P.+ 952 mm (2 mm decrease since 0:00 on September 20)	T.P.+ 961 mm (7 mm increase since 0:00 on September 20)	T.P.+ 784 mm (16 mm decrease since 0:00 on September 20)	T.P.+ 818 mm (1 mm decrease since 0:00 on September 20)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 249 mm (No change since 0:00 on September 20) T.P.+ 789 mm (1 mm increase since 0:00 on September 20) T.P.+ 2,985 mm (40 mm increase since 0:00 on September 20)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.