

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 22,)**

Water Level of the accumulated water (at 0:00 on September 22)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 920 mm (No change since 0:00 on September 21)	T.P.+ 770 mm (17 mm increase since 0:00 on September 21)	T.P.+ 896 mm (4 mm increase since 0:00 on September 21)
	Water level of Reactor Building	T.P.+ 948 mm (4 mm decrease since 0:00 on September 21)	T.P.+ 949 mm (12 mm decrease since 0:00 on September 21)	T.P.+ 802 mm (18 mm increase since 0:00 on September 21)	T.P.+ 818 mm (No change since 0:00 on September 21)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 139 mm (110 mm decrease since 0:00 on September 21) T.P.+ 819 mm ( 30 mm increase since 0:00 on September 21) T.P.+ 3,023 mm (38 mm increase since 0:00 on September 21)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.