

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 23,)**

Water Level of the accumulated water (at 0:00 on September 23)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 920 mm (No change since 0:00 on September 22)	T.P.+ 782 mm (12 mm increase since 0:00 on September 22)	T.P.+ 900 mm (4 mm increase since 0:00 on September 22)
	Water level of Reactor Building	T.P.+ 948 mm (No change since 0:00 on September 22)	T.P.+ 956 mm (7 mm increase since 0:00 on September 22)	T.P.+ 816 mm (14 mm increase since 0:00 on September 22)	T.P.+ 817 mm (1 mm decrease since 0:00 on September 22)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 28 mm (111 mm decrease since 0:00 on September 22) T.P.+ 827 mm (8 mm increase since 0:00 on September 22) T.P.+ 3,061 mm (38 mm increase since 0:00 on September 22)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.