

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 26,)**

Water Level of the accumulated water (at 0:00 on September 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 913 mm (1 mm increase since 0:00 on September 25)	T.P.+ 775 mm (9 mm increase since 0:00 on September 25)	T.P.+ 895 mm (2 mm decrease since 0:00 on September 25)
	Water level of Reactor Building	T.P.+ 952 mm (10 mm increase since 0:00 on September 25)	T.P.+ 949 mm (16 mm increase since 0:00 on September 25)	T.P.+ 805 mm (5 mm increase since 0:00 on September 25)	T.P.+ 814 mm (No change since 0:00 on September 25)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -199 mm (132 mm decrease since 0:00 on September 25) T.P.+ 831 mm ( 2 mm increase since 0:00 on September 25) T.P.+ 2,857 mm (30 mm increase since 0:00 on September 25)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.