

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 27,)**

Water Level of the accumulated water (at 0:00 on September 27)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 913 mm (No change since 0:00 on September 26)	T.P.+ 787 mm (12 mm increase since 0:00 on September 26)	T.P.+ 901 mm (6 mm increase since 0:00 on September 26)
	Water level of Reactor Building	T.P.+ 951 mm (1 mm decrease since 0:00 on September 26)	T.P.+ 944 mm (5 mm decrease since 0:00 on September 26)	T.P.+ 819 mm (14 mm increase since 0:00 on September 26)	T.P.+ 814 mm (No change since 0:00 on September 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -256 mm (57 mm decrease since 0:00 on September 26) T.P.+ 832 mm (1 mm increase since 0:00 on September 26) T.P.+ 2,892 mm (35 mm increase since 0:00 on September 26)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.