

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on September 29,)**

Water Level of the accumulated water (at 0:00 on September 29)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 915 mm (2 mm increase since 0:00 on September 28)	T.P.+ 773 mm (14 mm decrease since 0:00 on September 28)	T.P.+ 892 mm (9 mm decrease since 0:00 on September 28)
	Water level of Reactor Building	T.P.+ 944 mm (7 mm decrease since 0:00 on September 28)	T.P.+ 972 mm (28 mm increase since 0:00 on September 28)	T.P.+ 817 mm (2 mm decrease since 0:00 on September 28)	T.P.+ 814 mm (No change since 0:00 on September 28)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -287 mm (31 mm decrease since 0:00 on September 28) T.P.+ 832 mm (No change since 0:00 on September 28) T.P.+ 2,927 mm (35 mm increase since 0:00 on September 28)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.