

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 0:00 on October 17,)**

Water Level of the accumulated water (at 0:00 on October 17)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	- Removal completed on March, 2017	T.P.+ 917 mm (4 mm increase since 0:00 on October 16)	T.P.+ 797 mm (12 mm increase since 0:00 on October 16)	T.P.+ 917 mm (3 mm increase since 0:00 on October 16)
	Water level of Reactor Building	T.P.+ 947 mm (12 mm increase since 0:00 on October 16)	T.P.+ 935 mm (31 mm decrease since 0:00 on October 16)	T.P.+ 835 mm (12 mm increase since 0:00 on October 16)	T.P.+ 803 mm (No change since 0:00 on October 16)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ -719 mm (147 mm decrease since 0:00 on October 16) T.P.+ 935 mm (2 mm increase since 0:00 on October 16) T.P.+ 2,862 mm (30 mm increase since 0:00 on October 16)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.